


**Inspection Photos (08-17-2018)**  
**Location Name: Rider Family Trust #1**  
**Facility ID: 10507, REM: 11300**




**Track excavator enlarging excavation**



**Tack excavator enlarging excavation**



**Inspection Photos (08-17-2018)**  
**Location Name: Rider Family Trust #1**  
**Facility ID: 10507, REM: 11300**



**Ground water in excavation**



**Pipes encountered during excavation**



**Inspection Photos (08-17-2018)**  
**Location Name: Rider Family Trust #1**  
**Facility ID: 10507, REM: 11300**



**Impacted soil stock piled on a liner**



**Loading truck for offsite disposal**