

Inspection Photos (08-23-2018)
Location Name: Rider Family Trust #1
Facility ID: 10507, REM 113000



Photo 1.
Excavation activities.



Photo 2.
Ground water infiltrating open excavation.

Inspection Photos (08-23-2018)
Location Name: Rider Family Trust #1
Facility ID: 10507, REM 113000



Photo 3.
Excavating smear zone.



Photo 4.
Spoil pile on liner.

Inspection Photos (08-23-2018)
Location Name: Rider Family Trust #1
Facility ID: 10507, REM 113000



Photo 5.
Repaired access road.



Photo 6.
Vehicle tracking control gravel pad.

Inspection Photos (08-23-2018)
Location Name: Rider Family Trust #1
Facility ID: 10507, REM 113000



Photo 7.
Vehicle tracking control pad.



Photo 8.
Vehicle tracking control pad.

Inspection Photos (08-23-2018)
Location Name: Rider Family Trust #1
Facility ID: 10507, REM 113000



Photo 9.
Spring Gulch.



Photo 10.
Spring Gulch.