

## Inspection Photos

Location Name: Bunker 5&6 Tank Battery Location ID 307044, Spill ID #451318

Inspection Date: 8/24/2018



Photo 1 – Crude oil AST and tank battery sign.




Photo 2 – Leaky fitting at crude oil AST.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

## Inspection Photos

Location Name: Bunker 5&6 Tank Battery Location ID 307044, Spill ID #451318

Inspection Date: 8/24/2018



Photo 3 – Unsued risers at crude oil AST.



Photo 4 – Produced Water AST.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources