

Inspection Photos
Location Name: Boies Ranch C-240 Pad
Location ID: #335678
Inspection Date: August 20, 2018



Photo #1 – Unused equipment (hoses, metal fitting) on north side of tank battery, looking east.



Photo #2 – Unused hose stored on north side of tank battery, near loadout.

Inspection Photos
Location Name: Boies Ranch C-240 Pad
Location ID: #335678
Inspection Date: August 20, 2018



Photo #3 – Hose manifold on south side of tank battery.



Photo #4 – Tank battery berm has been expanded to accommodate four (4) new tanks.

Inspection Photos
Location Name: Boies Ranch C-240 Pad
Location ID: #335678
Inspection Date: August 20, 2018



Photo #5 – Unused hoses stored on south side of tank battery.



Photo #6 – Cuttings stockpiled at SE corner of location.