

Inspection Photo
Magic 10-1 (P3)
API # 045-09462
Inspection # 689301836



Location Photo #1



Location Photo #2

**Inspection Photo
Magic 10-1 (P3)
API # 045-09462
Inspection # 689301836**



Location Photo #3



Location Photo #4, stained ground by separator.

**Inspection Photo
Magic 10-1 (P3)
API # 045-09462
Inspection # 689301836**



Location Photo #5, weeds



Location Photo #6, weeds




Inspection Photo
Magic 10-1 (P3)
API # 045-09462
Inspection # 689301836



Location Photo #7, weeds

**Inspection Photo
Magic 10-1 (P3)
API # 045-09462
Inspection # 689301836**



Location Photo #8, Leaking bonnet on master valve



Location Photo #9, leaking bonnet on master valve