

# Final Reclamation Inspection

August 24, 2018

Operator: CONTINENTAL RESOURCES INC - 10347

API: 05-123-33603

Inspection Document #: 682403918

Weld County, CO

NENE Section 8 T9N R61W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: Allenby #1-8H  
API: 05-123-33603



**Photo 1.** Photo taken east of the location, facing West. Well location was not constructed at the proposed location based off field observations.