

Interim Reclamation Inspection

August 24, 2018

Operator: SCHNEIDER ENERGY SERVICES INC- #76840

API #: 05-123-32780

Inspection Document #: 682403917

Weld County, CO

Lot 1 Section 4 T9N R61W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO

Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Newton #1-4H
API #: 05-123-32780



Photo 1. Photo taken of the Operator sign which is not reflective of the current operator.

Inspection Photos
Location Name: Newton #1-4H
API #: 05-123-32780



Photo 2. Photo taken from the eastern location. Multiple risers were observed where equipment was previously stored. Based on aerial imagery, equipment has been removed for nearly five years.

Inspection Photos
Location Name: Newton #1-4H
API #: 05-123-32780



Photo 3. Photo taken from the wellhead, facing South. See comments under Photo 2.

Inspection Photos
Location Name: Newton #1-4H
API #: 05-123-32780



Photo 4. Photo taken from the southeastern location, facing South. See comments under Photo 2.

Inspection Photos
Location Name: Newton #1-4H
API #: 05-123-32780



Photo 5. Photo taken from the north central location, facing East. Photo illustrates Canada thistle, a List B Colorado noxious weed. Operator needs to control and manage all List B Colorado noxious weeds.

Inspection Photos
Location Name: Newton #1-4H
API #: 05-123-32780



Photo 6. Photo taken from the northern location, facing West. See comments under Photo 5.