

## Inspection Photos

Location Name: Garden Creek 16-2314H Location ID 420661, Spill ID #456897

Inspection Date: 8/28/2018



Photo 1 – Tank Battery Sign



Photo 2- Southwest corner of tank batter containment, looking north.



## Inspection Photos

Location Name: Garden Creek 16-2314H Location ID 420661, Spill ID #456897

Inspection Date: 8/28/2018



Photo 3 – Southwest corner of tank battery, looking east.




Photo 4 – Base of produced water tank. Corrosion hole visible.



## Inspection Photos

Location Name: Garden Creek 16-2314H Location ID 420661, Spill ID #456897

Inspection Date: 8/28/2018



Photo 5 – Oil stained material within secondary containment. Southeast corner of tank battery looking west.




Photo 5 – Piping entering produced water tank, piping valves appear open.

