

Inspection Photos
Location Name:Adam B Unit#10
Location ID:320390



Photo#1 Production tank and produced water pit

Corrective Action: Amount not marked on pit. Unused Equipment needs to be removed (Unmarked 50 Gallon drum)



Photo#2 Separator and gas meter

Inspection Photos
Location Name:Adam B Unit#10
Location ID:320390



Photo#3Wellhead