

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

08/28/2018

Submitted Date:

08/28/2018

Document Number:

691200383

FIELD INSPECTION FORM

Loc ID 330637 Inspector Name: Evins, Bret On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Findings:

- 20 Number of Comments
- 3 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
251589	WELL	SI	06/01/2018	OW	123-19392	Malo 09-20	PR

General Comment:

[This is a WELL & BATTERY Inspection](#)

Location			
Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	CONTAINERS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unused equipment at pumping unit skid. (Back-pressure valve, control clock). Statewide unused equipment, weeds, waste, and trash requirements Refer to Rule 603.f for guidance.		
Corrective Action:	Comply with Rule 603.f .		Date: <u>09/27/2018</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	IGNITOR/COMBUSTOR		
Comment:	Barbed wire		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Iron panel		

Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Barbed wire		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Barbed wire		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Iron mesh panel		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Emission Control Device	# 1		
Comment:	Pilot is ON. Controls crude oil tanks VOCs.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Recycle pump		
Corrective Action:		Date:	
Type: Vertical Heater Treater	# 1		
Comment:	Treater & separator are surrounded by earth berms.		
Corrective Action:		Date:	
Type: Vertical Separator	# 1		
Comment:	2-phase separator		
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Gas Engine. Stained soil in engine house around gas engine in several areas. Mechanical Conditions. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		
Corrective Action:	Comply w/ Rule 605.d.	Date:	09/27/2018
Type: Ancillary equipment	# 2		
Comment:	CONTAINERS: 2 - 55 gal. metal drums (motor oil)		
Corrective Action:		Date:	

Tanks and Berms:					
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		
Comment: Uncovered oval opening on top of produced H2O vault near the back may risk animal ingress. Mechanical Conditions. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.					
Corrective Action: Comply w/ Rule 605.d.					Date: <u>10/03/2018</u>

Paint	
Condition	
Other (Content)	
Other (Capacity)	80 Bbls.
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment: Shares berms w/ crude oil tanks.				
Corrective Action:				Date:


Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	400 BBLS	STEEL AST		40.645535,-103.993283
Comment:					
Corrective Action:					Date:

Paint	
Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms				
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate
Comment: Shares berms w/ produced H2O vault.				
Corrective Action:				Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:	
Type	
Comment:	
Corrective Action:	Date:



Inspected Facilities

Facility ID: 251589 Type: WELL API Number: 123-19392 Status: SI Insp. Status: PR

Producing Well

Comment: PR. Pumping unit & gas engine are shut down. Production valves at wellhead are open to flowline. Observed gas sales meter indicating production of natural gas.

Corrective Action:

Date:

BradenHead

Comment: Bradenhead appears plumbed to surface.

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691200385	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4564772