

Inspection Photos
Location Name: Woolly 13-14
Location ID: 451458



Wellhead



Battery



Inspection Photos
Location Name: Wooly 13-14
Location ID: 451458



Separator



Rear of tank (areas of subsidence)

Inspection Photos
Location Name: Woolly 13-14
Location ID: 451458



West tank berm wall. Corrective Action: Repair or install berms or other secondary containment devices per Rule 605.a.(4).

