

# Session Report

8/28/2018

## Information Panel


Name	Divide creek compressor plant S018_BGR100002_28082018_132012
Start Time	8/28/2018 11:06:59 AM
Stop Time	8/28/2018 12:10:32 PM
Device Name	BGR100002
Model Type	SoundPro DL
Device Firmware Rev	R.13H
Comments	Wind was out of the SW @ about 10 mph. Distance from compressor building was 81 Feet. We took noise reading from SW corner inside the fence.

## Summary Data Panel

Description	Meter	Value	Description	Meter	Value
Leq	1	69.1 dB			
Exchange Rate	1	3 dB	Weighting	1	A
Response	1	SLOW	Bandwidth	1	OFF
Leq	2	83.1 dB			
Exchange Rate	2	3 dB	Weighting	2	C
Response	2	FAST			

## Logged Data Chart

Divide creek compressor plant S018\_BGR100002\_28082018\_132012: Logged Data Chart



## Calibration History

Date	Calibration Action	Level	Cal. Model Type	Serial Number	Cert. Due Date
8/28/2018 11:05:57 AM	Calibration	114.0			

