

Inspection Photos

08/29/2018

Operator: WHITING OIL & GAS CORPORATION -
96155

Location ID: 436769

Inspection Doc. Number: 682503788
Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: WHITING OIL & GAS CORPORATION - 96155
Location ID: 436769



Photo 1: Photo taken from the west end of the production are, facing east. Photo shows weed/vegetation growth next to the wells on location.



Photo 2: Photo taken from the western area of the production area, facing east. Photo shows areas of the location that have not been stabilized or reclaimed.

Inspection Photos
Operator: WHITING OIL & GAS CORPORATION - 96155
Location ID: 436769



Photo 3: Photo taken from the western area of the production area, facing south. Photo shows areas of the location that has not been stabilized or reclaimed.



Photo 4: Photo taken from the interim area, facing east. Photo shows reclamation in process.

Inspection Photos
Operator: WHITING OIL & GAS CORPORATION - 96155
Location ID: 436769



Photo 5: Photo taken from the northeast end of the location. Photo shows Canada thistle on location. This is a Colorado State listed noxious weed and needs to be managed.



Photo 6: Photo taken from the northeast end of the location, facing north. Photo shows Canada thistle on location. This is a Colorado State listed noxious weed and needs to be managed.

Inspection Photos
Operator: WHITING OIL & GAS CORPORATION - 96155
Location ID: 436769



Photo 7: Photo taken from areas just to the east of the wells. Photo shows Canada thistle rosette.



Photo 8: Photo taken from the south end of the location. Photo of cattle guard.