

**Inspection Photo**  
**Youberg SR 443-12**  
**API # 045-18422**  
**Inspection # 689301869**



**Location Photo #1**



**Location Photo #2**



**Inspection Photo  
Youberg SR 443-12  
API # 045-18422  
Inspection # 689301869**



**Location Photo #3**



**Location Photo #4, stained soil still by the wellheads**



**Inspection Photo**  
**Youberg SR 443-12**  
**API # 045-18422**  
**Inspection # 689301869**



**Location Photo #5, stained soil under valve**



**Location Photo #6, cleaned up stain?**



**Inspection Photo**  
**Youberg SR 443-12**  
**API # 045-18422**  
**Inspection # 689301869**



**Location Photo #7, cleaned up stain?**



**Location Photo #8, piping removed.**



**Inspection Photo  
Youberg SR 443-12  
API # 045-18422  
Inspection # 689301869**



**Location Photo #9, uncontrolled weeds in interim reclamation**



**Location Photo #10 , uncontrolled weeds in interim reclamation**

**Inspection Photo  
Youberg SR 443-12  
API # 045-18422  
Inspection # 689301869**



**Location Photo #11 , uncontrolled weeds in  
interim reclamation**