

# *Inspection Photos*

*Loc#335906*

*Operator: Caerus*

*Inspection Number: 692400072*

*Inspection Date: 8/22/2018*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location to Southwest.

August 22, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus N.Parachute Loc#335906





Photo#2:  
Overview of Interim Reclamation area & retention Pond.

August 22, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Caerus N.Parachute Loc#335906