

Inspection Photos
Location Name: Puckett-66S97W 25NWNE
Location ID: #335114
Inspection Date: August 28, 2018



Photo #1 – Well signs on south side of temporary tank battery. Note inadequate berm construction.



Photo #2 – Metal tank battery berm components have been removed as part of Remediation Project #11621.