

Inspection Photos

Operator: BP America

API: 05-067-06714

Date: 8/16/2018



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the southern portion of the project area from the southeastern corner facing westward.



Photo 3. View of the eastern portion of the project area from the southwestern corner facing northward.



Photo 4. View of rilling and sediment deposition in the southern project area.



Photo 5. View of the project area from the northeastern corner facing center. Tall kochia (*Kochia scoparia*) plants will dry and become debris, and therefore need to be removed.



Photo 6. Closeup view of tall (approximately 3.5 feet) kochia plants in the northern project area.