

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

08/29/2018

Submitted Date:

08/29/2018

Document Number:

691200387**FIELD INSPECTION FORM**Loc ID 305168 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 70385Name of Operator: SMITH ENERGY CORPAddress: 12706 SHILOH RDCity: GREELEY State: CO Zip: 80631**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**15 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

| Contact Name | Phone | Email | Comment |
|----------------|----------------|---------------------------|---------|
| Arthur, Denise | | denise.arthur@state.co.us | |
| Smith, Glenn | (970) 381-6253 | gsmithten@what-wire.com | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 274861 | WELL | SI | 06/01/2018 | OW | 123-22590 | CHINOOK 1 | SI |

General Comment:This is a WELL & BATTERY Inspection.

| Location | | | |
|--|---|-----------------|----------------------------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Access road from county road has heavy weed overgrowth. Refer to "Good Housekeeping" section of this FIR for CA items & due date. | | |
| Corrective Action | L | Date: | |
| Overall Good: <input type="checkbox"/> | | | |
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type | BATTERY | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Emergency Contact Number: | | | |
| Comment: | <input type="text"/> | | |
| Corrective Action: | <input type="text"/> | | Date: <input type="text"/> |
| Good Housekeeping: | | | |
| Type | WEEDS | | |
| Comment: | Access road from county road has heavy weed overgrowth. Entire tank battery, wellhead, meter run areas all have heavy weed overgrowth. Statewide unused equipment, weeds, waste, and trash requirements. 10 days for weeds. Refer to Rule 603.f for guidance. | | |
| Corrective Action: | Comply with Rule 603.f . | | Date: 09/10/2018 |
| Overall Good: <input type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: | <input type="text"/> | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Fencing/: | | | |
| Type | PUMP JACK | | |
| Comment: | Iron rod panel | | |
| Corrective Action: | | Date: | |
| Equipment: | | | |
| Type: Deadman # & Marked | # 4 | corrective date | |
| Comment: | 4 / 4-marked | | |

| | | | |
|---------------------|--|-------|--|
| Corrective Action: | | Date: | |
| Type: | # | | |
| Comment: | Refer to FIR #691200386 for additional Equipment info. | | |
| Corrective Action: | | Date: | |
| Type: Prime Mover | # 1 | | |
| Comment: | Gas Engine. | | |
| Corrective Action: | | Date: | |
| Type: Gas Meter Run | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Pump Jack | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|--|----------|---------------------|---------|--------|
| | | | CENTRALIZED BATTERY | | , |
| Comment: | This Centralized Battery services 3 Locations (327106, 305168, 332130). Refer to FIR #691200386 for additional Tanks & Berms info. | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|--|
| Condition | |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| | | | | |
| Comment: | | | | |
| Corrective Action: | | | | Date: |

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|-----------------------------------|----------|-----------|---------|-----------------------|
| CRUDE OIL | 1 | 300 BBLS | STEEL AST | | 40.579280,-103.732120 |
| Comment: | Maintenance tank. | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|--|
| Condition | |
| Other (Content) | |
| Other (Capacity) | |
| Other (Type) | |

Berms

| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|------|----------|---------------------|---------------------|-------------|
| | | | | |

Inspector Name: Evins, Bret

| | | | | | |
|--|----------|------------------|-----------------|----------|--------|
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Comment: Shares berms w/ produced H2O tank. | | | | | |
| Corrective Action: | | | | | Date: |
| Contents | # | Capacity | Type | Tank ID | SE GPS |
| PRODUCED WATER | 1 | OTHER | PBV STEEL | | , |
| Comment: Used for draining produced water from crude oil maintenance tank. | | | | | |
| Corrective Action: | | | | | Date: |

Paint

| | |
|------------------|----------|
| Condition | |
| Other (Content) | |
| Other (Capacity) | 80 Bbls. |
| Other (Type) | |

Berms

| | | | | | |
|--|----------|---------------------|---------------------|-------------|-------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Earth | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Comment: Shares berms w/ crude oil maintenance tank. | | | | | |
| Corrective Action: | | | | | Date: |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | |
|--------------------|-------|
| Type | |
| Comment: | |
| Corrective Action: | Date: |

Inspected FacilitiesFacility ID: 274861 Type: WELL API Number: 123-22590 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: PRODUCTION RECORDS

Comment: SI. Records indicate SI since 06/2018. Observed production valves to flowline at well were closed.

Corrective Action:

Date:

BradenHead

Comment: Bradenhead is NOT plumbed to surface. Plumb bradenhead to surface. 30 days. Mechanical Conditions
Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Corrective Action:

Comply w/ Rule 605.d.Date: 09/28/2018

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment | User | Date |
|--|--------|------------|
| Previous CA items referenced in FIR #684902193 dated 9/1/2016 have been addressed. | evinsb | 08/29/2018 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 401748893 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4565916 |
| 691200388 | Site photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4565913 |