

B&V 24B 07-07-95
API# 05-045-22705
Inspection# 689701762



Well heads photo.

B&V 24B 07-07-95
API# 05-045-22705
Inspection# 689701762



Open conductor on location with no permit.
No sign for identification of undrilled well.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

B&V 24B 07-07-95
API# 05-045-22705
Inspection# 689701762



The public road used to access the site not on sign. Phone number at which the operator can be reached at all times is missing a digit.



The public road used to access the site not on sign. Phone number at which the operator can be reached at all times is missing a digit.