

Inspection Photos

Loc#335557

Operator: Terra

Inspection Number: 692400104

Inspection Date: 8/31/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from entry to Southwest.

August 31, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: TEP Jolley KPLoc#335557



Photo#2:
View over Location from Southwest corner to Northeast.

August 31, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: TEP Jolley KPLoc#335557



Photo#3:

Areas that should be in Interim Rec are hard-packed, graveled and weed infested. Insert shows close up of ground conditions.

Photo#4:

August 31, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: TEP Jolley KPLoc#335557



Photo#5:
Sides of access roads are Kochia Infested.

August 31, 2018



Photo#6:
Sides of access roads are Kochia Infested.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: TEP Jolley KPLoc#335557



Photo#7:

Perennial Vegetation is established along base of Fill slopes. Wattles no longer serviceable or needed have had casing removed & material broken up.



Photo#8:

August 31, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: TEP Jolley KPLoc#335557