

Inspection Photos
Location Name: Gregory 0780 1-09H
Location ID: 439603



Photo 1. Tank label incomplete.



**Photo 2. Storage of oily fluid without containment.
Stained soil surrounding container.**

Inspection Photos
Location Name: Gregory 0780 1-09H
Location ID: 439603



Photo 3. Stained soil in radius around wellheads.



Photo 4. Stained soil at wellhead, plastic bucket at wellhead.

Inspection Photos
Location Name: Gregory 0780 1-09H
Location ID: 439603



Photo 5. Close-up of bucket contents and soil staining.



Photo 6. Stained soil around wellheads. Wellhead signs missing or knocked over.

Inspection Photos
Location Name: Gregory 0780 1-09H
Location ID: 439603



Photo 7. Stained soil at wellhead.



Photo 8. Wellhead sign not readable.

Inspection Photos
Location Name: Gregory 0780 1-09H
Location ID: 439603



Photo 9. Bucket and sample jars stored at separator.



Photo 10. Close-up of bucket contents.

Inspection Photos
Location Name: Gregory 0780 1-09H
Location ID: 439603



Photo 11. Storage of sampling bottles, stained soil.



Photo 12. Storage of sampling bottles, stained soil.