

Inspection Photos

Location Name: CC 604-41-32 Pad

Location ID: #335902

Inspection Date: August 29, 2018



Photo #1 – Facility sign located at entrance to location.



Photo #2 – Looking north at frac tanks stored on location. Note red arrow points to excavation in center of pad.

Inspection Photos

Location Name: CC 604-41-32 Pad

Location ID: #335902

Inspection Date: August 29, 2018



Photo #3 – Frac tanks stored on location lacked secondary containment devices on inspection date.



Photo #4 – Unidentified well casing with welded cap is located in center of excavation.

