

Inspection Photos
Location Name: Dill Gulch 1-17
API: 05-107-06019



Photo 1. Overview of location taken at entrance facing northeast.

Inspection Photos
Location Name: Dill Gulch 1-17
API: 05-107-06019



Photo 2. Soil staining still present at wellhead.



Photo 3. Incomplete battery sign.

Inspection Photos
Location Name: Dill Gulch 1-17
API: 05-107-06019



Photo 4. Soil staining still present at tank loadout.



Photo 5. Soil staining still present in tank battery.

Inspection Photos
Location Name: Dill Gulch 1-17
API: 05-107-06019



Photo 6. Soil staining still present at tank base.



Photo 7. Soil staining still present at tank loadout.