

Inspection Photos

Loc#335447

Operator: Terra

Inspection Number: 692400109

Inspection Date: 8/31/2018





Photo#1:
Overview of Location from entry to South.

August 31, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: TEP Jolley Loc#335447



Photo#2:

Area behind Boulder barrier on East side of Location that is compacted & weedy. Arrow indicates materials/soil that appears to have been dumped on Cut slope shown in Photo#3.

August 31, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: TEP Jolley Loc#335447



Photo#3:
View of Cut slope and materials/soil pile. Insert is of other weedy area of Cut slope.

August 31, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: TEP Jolley Loc#335447



Photo#4:

Photo#5:

Weed growth on Pad is subject of CA in Previous Field Inspection; these areas receive very limited or no vehicle traffic ; creating a perfect environment for opportunist annual weeds.

August 31, 2018