

Inspection Photos
Location Name: VONASEK #7
Facility ID: 241440



Photo 1. Wellhead/Stained soil around wellhead all the way into the weeds to the North



Photo 2. Tank battery/Stained soil near crude oil load out

Inspection Photos
Location Name: VONASEK #7
Facility ID: 241440



Photo 3. Weed overgrowth on ROW to well



Photo 4. Weeds inside berms at tank battery

Inspection Photos
Location Name: VONASEK #7
Facility ID: 241440



Photo 5. Trash on East edge of tank battery location



Photo 6. Unused unmarked riser near meter at tank battery

Inspection Photos
Location Name: VONASEK #7
Facility ID: 241440



Photo 1. Wellhead



Photo 2. Tank battery

