

Inspection Photos

Loc#335207

Operator: Terra

Inspection Number: 692400113

Inspection Date: 8/31/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location from entry to Northeast.

August 31, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: TEP Jolley KP Loc#335207



Photo#2:
View over North Interim Reclamation area.

August 31, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: TEP Jolley KP Loc#335207



Photo#3:
Views over portions of North Interim Reclamation area.

Photo#4:

August 31, 2018



Photo#5: Photo#6:
Close up views of ground conditions & vegetation in North Reclamation area.

August 31, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: TEP Jolley KP Loc#335207