

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:

401756469

Date Received:

09/07/2018

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

2 of 4 CAs from the FIR responded to on this Form

2 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 10447

Name of Operator: URSA OPERATING COMPANY LLC

Address: 792 BUCKHORN DR

City: RIFLE State: CO Zip: 81650

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Knudson, Dwayne

970-456-3335

dknudson@ursaresources.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 689301780

Inspection Date: 08/21/2018

FIR Submit Date: 08/21/2018

FIR Status: _____

Inspected Operator Information:

Company Name: URSA OPERATING COMPANY LLC

Company Number: 10447

Address: 1600 BROADWAY ST STE 2600

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 311695

Location Name: GENTRY-66S92W Number: 17SESE County: GARFIELD

Qtrqr: SESE Sec: 17 Twp: 6S Range: 92W Meridian: 6

Latitude: 39.520698 Longitude: -107.683182

FACILITY - API Number: 05-045- -00 Facility ID: 294141

Facility Name: GENTRY Number: C9

Qtrqr: SESE Sec: 17 Twp: 6S Range: 92W Meridian: 6

Latitude: 39.520698 Longitude: -107.683182

CORRECTIVE ACTIONS:

1 CA# 118035

Corrective Action: Repair or install berms or other secondary containment devices per Rule 605.a.(4).

Date: 09/21/2018

Response: CA COMPLETED

Date of Completion: 08/30/2018

Operator
Comment:

Holes in secondary containment have been repaired. See photo

COGCC Decision: _____

Corrective Action:	Comply with Rule 603.f .
--------------------	--------------------------

Response: CA COMPLETED

Operator Comment:	Weeds were mowed - see photos.
-------------------	--------------------------------

COGCC Decision:

Comment:	Please send to Darin Holtz
----------	----------------------------

Print Name: Dwayne Knudson

Signed: _____

Title: Environmental Manager

Date: 9/7/2018 10:15:34 AM

<u>Document Number</u>	<u>Description</u>
------------------------	--------------------

401756473	Containment Patch photo
401756691	Mowed photo
401756692	Mowed photo
401756693	Mowed photo
401756694	Mowed photo

Page 2 of 2