

## Inspection Photos

**Location Name:** New Cache FH SESE PAD / 8-40D

**Location #:** 310877



**Photo #1**

**New Cache 8-44** (API 05-123-27176) wellhead

*From previous FIR*



**Photo #2**

**New Cache 8-43, 8-44, Cache 8-54** Battery

*From previous FIR*



## Inspection Photos

**Location Name:** New Cache FH SESE PAD / 8-40D

**Location #:** 310877



**Photo #3**

**New Cache 8-43, 8-44, Cache 8-54 Battery**

**No sign with contact info or Emergency # at Batt**

*From previous FIR*



**Photo #4**

**New Cache 8-43, 8-44, Cache 8-54 Battery**

**No sign with contact info or Emergency # at Batt**



## Inspection Photos

**Location Name:** New Cache FH SESE PAD / 8-40D

**Location #:** 310877



**Photo #5**

**New Cache 8-43, 8-44, Cache 8-54 Battery**  
**Stormwater erosion SW of separators**

*From previous FIR*



**Photo #6**

**New Cache 8-43, 8-44, Cache 8-54 Battery**  
**Stormwater erosion SW of separators**



## Inspection Photos

Location Name: New Cache FH SESE PAD / 8-40D

Location #: 310877



**Photo #7**

**New Cache 8-43, 8-44, Cache 8-54 Battery**

**No contents / capacity shown on fiberglass vault**

*From previous FIR*



**Photo #8**

**New Cache 8-43, 8-44, Cache 8-54 Battery**

**No contents / capacity shown on fiberglass vault**

