

Falcon Seaboard 11-90-11 #2 Corrective Actions



Photo 1. Chemical Tank label had fallen off; it has been replaced.



Photo 2. Stained soil has been cleaned up. Stains will be monitored as drilling and production equipment is moved on and off the location, and removed w needed.