

Inspection Photos

Location Name: Federal Osprey- 68N60W / 35NENW

Location #: 331181



Colorado Oil & Gas Conservation Commission
40.62258, -104.06814, 1485.0m, 57°
2018/09/07 04:13:03 PM

Photo #1

Federal Osprey 35-3 (API # 05-123-20272) Spill

Flow line leak underneath well access road

Looking East



Colorado Oil & Gas Conservation Commission
40.62256, -104.06766, 1484.0m, 284°
2018/09/07 04:13:45 PM

Photo #2

Federal Osprey 35-3 Spill

Flow line leak underneath well access road

Looking West



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Federal Osprey- 68N60W / 35NENW

Location #: 331181



Colorado Oil & Gas Conservation Commission
40.62257, -104.06778, 1477.0m, 273°
2018/09/07 04:13:59 PM

Photo #3

Federal Osprey 35-3 Spill

Flow line leak underneath well access road

Looking West



Colorado Oil & Gas Conservation Commission
40.62238, -104.0614, 1477.0m, 49°
2018/09/07 04:55:48 PM

Photo #4

Federal Osprey 35-3 wellhead

Vac-Truck evacuating flowline leak fluids downstream



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Federal Osprey- 68N60W / 35NENW

Location #: 331181



Photo #5

Federal Osprey 35-3 Spill

Video of this active spill will be a separate attachment

Looking West



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources