

Inspection Photos

Location Name: Trail Ridge Pit 11-5-697

Location ID: #450948

Inspection Date:



Photo #1 - Sign affixed to gate on south side of pit. Gate was open on inspection date to allow access for pressure testing.



Photo #2 – Electronic leak detection system visible on west side of pit.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: Trail Ridge Pit 11-5-697

Location ID: #450948

Inspection Date:



Photo #3 – Overview of pit from NW corner.



Photo #4 – Hoses in SE corner of pit were in direct contact with liner on inspection date.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Trail Ridge Pit 11-5-697
Location ID: #450948
Inspection Date:



Photo #5 – View of tank battery from NW corner.




Photo #6 – Tank battery loadout hose stored inside of loadout containment device prevents direct contact with liner. Note wooden block stored beneath loadout container.

Inspection Photos
Location Name: Trail Ridge Pit 11-5-697
Location ID: #450948
Inspection Date:




Photo #7 – One of several wooden blocks stored inside of tank battery berm.



Photo #8 – Unused separators located north of pit.

Inspection Photos
Location Name: Trail Ridge Pit 11-5-697
Location ID: #450948
Inspection Date:



Photo #9 – Separator located southwest of pit.



Photo #10 – View of flowline manifold with generators located south of pit.