

Inspection Photos
Location Name: Dwight Sossaman A #2
API: 05-067-08982



Dwight Sossaman A #2 production equipment.



Swath of oil stained gravel near well head.

Inspection Photos
Location Name: Dwight Sossaman A #2
API: 05-067-08982



Oil stained soil below pump.



Equipment is tagged out.