

Inspection Photos

09/05/2018

Operator: FOUNDATION ENERGY
MANAGEMENT LLC - 10112

Location ID: 455471

Inspection Doc. Number: 682503868
Weld County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC



Photo 1: Photo taken from southern area of the location. Photo shows Diffuse Knapweed has not been sufficiently managed or removed from location.



Photo 2: Photo taken from southern area of the location, facing north. Photo shows Diffuse Knapweed has not been sufficiently managed or removed from location.



Photo 3: Photo taken from southern area of the location, facing southwest. Photo shows Diffuse Knapweed has not been sufficiently managed or removed from location.



Photo 4: Photo taken from southern area of the location, facing north. Photo shows Diffuse Knapweed has not been sufficiently managed or removed from location.

Inspection Photos
Operator: FOUNDATION ENERGY MANAGEMENT LLC - 10112
Location ID: 455471



Photo 5: Photo taken from central area of the location, facing east. Photo shows Diffuse Knapweed has not been sufficiently managed or removed from location.



Photo 6: Photo taken from western area of the location. Photo shows Diffuse Knapweed has not been sufficiently managed or removed from location.