

# Inspection Photos

09/05/2018

Operator: FOUNDATION ENERGY  
MANAGEMENT LLC - 10112

Location ID: 327558

Inspection Doc. Number: 682503872  
Weld County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC



**Photo 1:** Photo taken from northwestern area of the location, facing south. Photo shows Diffuse Knapweed has not been sufficiently managed or removed from location.



**Photo 2:** Photo taken from western area of the location. Photo shows Diffuse Knapweed has not been sufficiently managed or removed from location.



**Photo 3:** Photo taken from the southwestern area of the location. Photo shows Diffuse Knapweed has not been sufficiently managed or removed from the location..



**Photo 4:** Photo taken from the south end of the location, facing north. Photo shows Diffuse Knapweed has not been sufficiently managed or removed from the location.



**Photo 5:** Photo taken from the southeast end of the location. Photo shows Diffuse Knapweed has not been sufficiently managed or removed from location.



**Photo 6:** Photo taken from the access road, facing northeast. Photo shows Diffuse Knapweed has not been sufficiently managed or removed from the access road.