

**N. PARACHUTE MF05D E09 696**

**API# 05-045-14938**

**Inspection# 689701783**



**Battery signs obstructed by weeds.**

**N. PARACHUTE MF05D E09 696**

**API# 05-045-14938**

**Inspection# 689701783**



**Tank hatch is open and unattended..**



**N. PARACHUTE MF05D E09 696**

**API# 05-045-14938**

**Inspection# 689701783**



**Waddles need maintained/repared**



**Waddles need maintained/repared**



**N. PARACHUTE MF05D E09 696**

**API# 05-045-14938**

**Inspection# 689701783**



**Waddles need maintained/repared**



**Waddles need maintained/repared**

**N. PARACHUTE MF05D E09 696**  
**API# 05-045-14938**  
**Inspection# 689701783**



No label



No label



**N. PARACHUTE MF05D E09 696**

**API# 05-045-14938**

**Inspection# 689701783**



**Leaking bull plug cap.**



**Leaking bull plug cap.**



**Spill/stain on ground of meter shed.**