

Inspection Photos

Location Name: SRC Murdock Facility Location 429711, DCP Spill ID #457249

Inspection Date: 9/7/2018



Photo 1 – Murdock Facility Sign



Photo 2 – Impacted surface material between separators and ASTs



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: SRC Murdock Facility Location 429711, DCP Spill ID #457249

Inspection Date: 9/7/2018



Photo 3 – Impacted surface material near AST containment



Photo 4 – Impacted material near and within AST containment



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: SRC Murdock Facility Location 429711, DCP Spill ID #457249

Inspection Date: 9/7/2018



Photo 5 – Impacted grass in pasture west of location, looking northwest



Photo 6 – Impacted grass in pasture west of location, looking south



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources