

A photograph of an excavation site. In the upper right, a yellow excavator bucket is partially visible, having just dug into the earth. The soil is a mix of light brown and dark, crumbly material. A green pipe or rod is visible on the left side of the excavation. The bottom of the excavation shows a layer of dark, hydrocarbon-stained soil. The text overlay provides context for the location and the nature of the contamination.

battery facility 451374  
hydrocarbon stained soil in excavation  
subsequent to PW vessel removal and before impacted soil removal

9.10.2018 11:38