

Inspection Photos
Location Name: UPRR 42 PAN AM AE #1
Facility ID: 240933



Photo 1. Wellhead

Photo 2. Unused equipment

Inspection Photos
Location Name: UPRR 42 PAN AM AE #1
Facility ID: 240933



Photo 3. Faulty equipment/stained soil