

Inspection Photos
Location Name: RUSSELL, TOM L. E #1
Facility ID: 240864



Photo 1. Wellhead



Photo 2. Tank battery

Inspection Photos
Location Name: RUSSELL, TOM L. E #1
Facility ID: 240864



Photo 3. Stained soil near west edge of east crude oil tank.



Photo 4. Unmarked unused riser southeast of east crude oil tank.

Inspection Photos
Location Name: RUSSELL, TOM L. E #1
Facility ID: 240864



Photo 5. Staining on valve and soil on west crude oil tank.



Photo 6. Unmarked unused riser southwest of west crude oil tank.

Inspection Photos
Location Name: RUSSELL, TOM L. E #1
Facility ID: 240864



Photo 7. Leaking valve on riser west of heated separators.



Photo 8. Unused equipment

Inspection Photos
Location Name: RUSSELL, TOM L. E #1
Facility ID: 240864



Photo 9. Stained soil under north heated separator



Photo 8. Unmarked unused riser near tank battery sign.