

Inspection Photos
Location Name: WALTER HUNZIKER #1
Facility ID: 239636



Photo 1. Wellhead



Photo 2. Tank battery

Inspection Photos
Location Name: WALTER HUNZIKER #1
Facility ID: 239636



Photo 3. Weeds around crude oil tank



Photo 3. Weeds around small tank/ no labels

Inspection Photos
Location Name: WALTER HUNZIKER #1
Facility ID: 239636



Photo 3. Weeds around heated separator