

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/10/2018

Submitted Date:

09/11/2018

Document Number:

689701786**FIELD INSPECTION FORM**

Loc ID 335560	Inspector Name: LONGWORTH, MIKE	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____
Operator Information: OGCC Operator Number: <u>10456</u> Name of Operator: <u>CAERUS PICEANCE LLC</u> Address: <u>1001 17TH STREET #1600</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>			
Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 20 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested			

Contact Information:

Contact Name	Phone	Email	Comment
, Caerus Piceance		COGCC.inspections@caerusoilandgas.com	Piceance inspections only
Pesicka, Conor		conor.pesicka@state.co.us	
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284554	WELL	PR	05/02/2006	GW	045-12211	N.PARACHUTE MF02C D09A 696	PR
284555	WELL	PR	09/01/2007	GW	045-12210	N.PARACHUTE MF02A D09A 696	PR
284556	WELL	PR	03/28/2007	GW	045-12209	N. PARACHUTE MF20C D09A696	PR
284557	WELL	PR	05/02/2006	GW	045-12208	N.PARCHUTE MF07C D09A 696	PR
284558	WELL	SI	08/01/2016	GW	045-12207	N.PARACHUTE MF07A D09A 696	SI
284559	WELL	PR	05/02/2006	GW	045-12206	N.PARACHUTE MF06C D09A 696	PR
284560	WELL	PR	08/01/2017	GW	045-12205	N.PARACHUTE MF 05B D09A 696	PR
289509	WELL	PR	02/28/2007	GW	045-13793	N. PARACHUTE MF20A D09A 696	PR
297094	WELL	PR	06/01/2009	GW	045-16299	N. PARACHUTE MF02B-9 D09A 69	PR
297095	WELL	SI	05/01/2018	GW	045-16300	N. PARACHUTE MF03C-9 D09A 69	SI
297096	WELL	PR	04/29/2009	GW	045-16301	N. PARACHUTE MF03A-9 D09A 69	PR
297097	WELL	PR	05/09/2009	GW	045-16302	N. PARACHUTE MF03D-9 D09A 69	PR
297099	WELL	SI	09/01/2017	GW	045-16304	N. PARACHUTE MF04D-9 D09A 69	SI
297100	WELL	PR	04/09/2009	GW	045-16305	N. PARACHUTE MF04A-9 D09A 69	PR
297101	WELL	PR	06/01/2009	GW	045-16306	N. PARACHUTE MF04C-9 D09A 69	PR

299810	WELL	PR	07/03/2009	GW	045-17757	N. PARACHUTE MF06B-9 D09A 69	PR
299811	WELL	PR	06/29/2009	GW	045-17758	N. PARACHUTE MF06C-9 D09A 69	PR
299812	WELL	PR	07/03/2009	GW	045-17759	N. PARACHUTE MF05D-9 D09A 69	PR
299813	WELL	PR	06/27/2009	GW	045-17760	N. PARACHUTE MF05B-9 D09A 69	PR

General Comment:

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action		Date:	

Overall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Battery sign obstructed by weeds.		
Corrective Action:	Install sign to comply with Rule 210.e.	Date:	10/12/2018

Emergency Contact Number:			
Comment:	970-285-2615		
Corrective Action:		Date:	

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Ancillary equipment	# 3		
Comment:	Chemical containers at meter sheds.		
Corrective Action:		Date:	
Type: Plunger Lift	# 19		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 19		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 19		

Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	<100 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	80 bbls	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	284554	Type:	WELL	API Number:	045-12211	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	284555	Type:	WELL	API Number:	045-12210	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	284556	Type:	WELL	API Number:	045-12209	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	284557	Type:	WELL	API Number:	045-12208	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	284558	Type:	WELL	API Number:	045-12207	Status:	SI	Insp. Status:	SI
Facility ID:	284559	Type:	WELL	API Number:	045-12206	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	284560	Type:	WELL	API Number:	045-12205	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	289509	Type:	WELL	API Number:	045-13793	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing well								
Corrective Action:						Date:			
Facility ID:	297094	Type:	WELL	API Number:	045-16299	Status:	PR	Insp. Status:	PR

<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:				Date:
Facility ID:	297095	Type:	WELL	API Number: 045-16300 Status: SI Insp. Status: SI
Facility ID:	297096	Type:	WELL	API Number: 045-16301 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:				Date:
Facility ID:	297097	Type:	WELL	API Number: 045-16302 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:				Date:
Facility ID:	297099	Type:	WELL	API Number: 045-16304 Status: SI Insp. Status: SI
Facility ID:	297100	Type:	WELL	API Number: 045-16305 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:				Date:
Facility ID:	297101	Type:	WELL	API Number: 045-16306 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:				Date:
Facility ID:	299810	Type:	WELL	API Number: 045-17757 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:				Date:
Facility ID:	299811	Type:	WELL	API Number: 045-17758 Status: PR Insp. Status: PR
<u>Producing Well</u>				
Comment:	Producing well			
Corrective Action:				Date:
Facility ID:	299812	Type:	WELL	API Number: 045-17759 Status: PR Insp. Status: PR

Producing Well			
Comment:	Producing well		
Corrective Action:		Date:	
Facility ID:	299813	Type:	WELL
API Number:	045-17760	Status:	PR
Insp. Status:	PR		
Producing Well			
Comment:	Producing well		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass					
Gravel	Pass					
Compaction	Pass					
		Compaction	Pass			
		Ditches	Pass			
				Material Handling And Spill Prevention	Pass	
		Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689701790	Inspection 689701786 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4576500