

Location Name: Berenergy Corporation – Merino 1 (075-09094)

Inspection Date: 8/13/2018



Photo # - 1

View south at scraped soils in the vicinity of the former separator



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Berenergy Corporation – Merino 1 (075-09094)

Inspection Date: 8/13/2018



Photo # - 2

View southeast at scraped soils in the vicinity of the former oil tanks



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Berenergy Corporation – Merino 1 (075-09094)

Inspection Date: 8/13/2018



Photo # - 2

View south at production pit



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Location Name: Berenergy Corporation – Merino 1 (075-09094)

Inspection Date: 8/13/2018



Photo # - 2

View north at oil stained soils in the vicinity of the former wellhead/pumping unit



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources