

# Interim Reclamation Inspection

September 5, 2018

Operator: NOBLE ENERGY INC- #100322

Location ID: 329064

Inspection Document #: 682403982

Weld County, CO

SWSE Section 14 T4N R65W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: SALLEE #14-43 (Tank battery)  
Location ID: 329064



**Photo 1.** Photo taken from the southeast battery location, facing West. Operator has failed to control and manage weeds per Rule 603.f.



**Photo 2.** Photo taken from the northern battery location, facing West. See comments under Photo 1.