

Location Name: P. O. & G. Operating, LLC – Marick 1A Battery  
Inspection Date: 8/23/2018



Photo # - 6

View north at east wall of first production pit (107562) – oil emulsion accumulating against east wall of pit, prevailing wind from the west



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: P. O. & G. Operating, LLC – Marick 1A Battery  
Inspection Date: 8/23/2018



Photo # - 2

Closeup view at east wall of first production pit (107562) – oil emulsion accumulating against east wall of pit, prevailing wind from the west



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources