

Inspection Photos  
Location Name: Dwinell 1  
API: 05-057-05129



**Photo 1. Overview of location taken at entrance facing southeast.**



**Photo 2. Pit.**



Inspection Photos  
Location Name: Dwinell 1  
API: 05-057-05129



**Photo 3. Land farm area.**



**Photo 4. Equipment stored on location.**



Inspection Photos  
Location Name: Dwinell 1  
API: 05-057-05129



**Photo 5. Equipment stored on location.**



**Photo 6. Equipment stored on location.**



Inspection Photos  
Location Name: Dwinell 1  
API: 05-057-05129



Photo 7. Noxious weeds on location.



Photo 8. Annual weeds on location, wellhead housing door.



Inspection Photos  
Location Name: Dwinell 1  
API: 05-057-05129




**Photo 9. Stained soil at tank connection.**



**Photo 10. Close-up of stained soil.**



Inspection Photos  
Location Name: Dwinell 1  
API: 05-057-05129



**Photo 11. Staining down tank side.**



**Photo 12. Low spot in berm.**



Inspection Photos  
Location Name: Dwinell 1  
API: 05-057-05129



**Photo 13. Incomplete tank label.**



**Photo 14. Apparent Methanol spill.**



Inspection Photos  
Location Name: Dwinell 1  
API: 05-057-05129



**Photo 15. Path of methanol spill.**



**Photo 16. Terminus of methanol spill pathway looking towards container.**