

Inspection Photos
Location Name: Visintainer 11-6-8-90
API: 05-081-07239



Photo 1. Overview of location taken at entrance facing south.



Photo 2. Incorrect emergency contact information on location signs.

Inspection Photos
Location Name: Visintainer 11-6-8-90
API: 05-081-07239



Photo 3. Methanol container labeled as 500 BBL tank.



Photo 4. Incorrect emergency contact information on location signs.