

Location Name: Ward and Son Operating – State #4 Battery (Spill #456489)  
Inspection Date: 8/23/2018



Photo # - 1

Location Name: Ward and Son Operating – State #4 Battery (Spill #456489)  
Inspection Date: 8/23/2018



Photo # - 2

View northwest at oil tank battery – Spill 446492 and 456489 location



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: Ward and Son Operating – State #4 Battery (Spill #456489)  
Inspection Date: 8/23/2018



Photo # - 3

View west at oil tank battery – Spill 446492 and 456489 location



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: Ward and Son Operating – State #4 Battery (Spill #456489)  
Inspection Date: 8/23/2018



Photo # - 4

View east across former oil skim pit (107554) excavation



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: Ward and Son Operating – State #4 Battery (Spill #456489)  
Inspection Date: 8/23/2018



Photo # - 5

View west across production pit ID 107554



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Location Name: Ward and Son Operating – State #4 Battery (Spill #456489)  
Inspection Date: 8/23/2018



Photo # - 6

View north at impacted soil stockpile to be removed



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources