

Inspection Photo
GGU 5-31B
API # 045-09442
Inspection # 689301901



Location Photo #1



Location Photo #2

**Inspection Photo
GGU 5-31B
API # 045-09442
Inspection # 689301901**



Location Photo #3, unmarked anchor on North side of location in grass.



Location Photo #4, unmarked anchor near burner.

