

Inspection Photos  
Location Name: MARTIN T HART UNIT F 1  
Facility ID: 240907



Photo 1. Wellhead



Photo 2. Tank battery



**Inspection Photos**  
**Location Name: MARTIN T HART UNIT F 1**  
**Facility ID: 240907**



**Photo 3. Stained soil near east crude oil tank.**



**Photo 4. Unmarked unused riser/no lock out tag out**



**Inspection Photos**  
**Location Name: MARTIN T HART UNIT F 1**  
**Facility ID: 240907**



**Photo 5. Photo from previous inspection**



**Photo 6. Stained soil from previous photo still present**

**Inspection Photos**  
**Location Name: MARTIN T HART UNIT F 1**  
**Facility ID: 240907**



**Photo 7. Pipe looks to be seeping**



**Photo 8. Pipe looks to be seeping**