

Inspection Photos
Location Name: MARTIN T. HART UNIT C 2
Facility ID: 243058



Colorado Oil & Gas Conservation Commission
40.10484, -104.89271, 1531.0m, 172°
2018/09/12 12:57:37

Photo 1. Wellhead



Colorado Oil & Gas Conservation Commission
40.10238, -104.89243, 1547.0m, 171°
2018/09/12 13:42:54

Photo 2. Tank battery

Inspection Photos
Location Name: MARTIN T. HART UNIT C 2
Facility ID: 243058



Photo 3. Weeds on ROW & around wellhead